

APP CRS	Rwy Idg	7569
055°	TDZE	708
	Apt Elev	727

RNAV (RNP) Z RWY 5
BUFFALO NIAGARA INTL (BUF)

For uncompensated Baro-VNAV systems, procedure NA below -18°C (0°F) or above 54°C (130°F). GPS required. For inoperative MALSR, increase RNP 0.10 all Cats visibility to 1¼. For inoperative MALSR, increase RNP 0.30 all Cats visibility to 1%. MALSR				MISSED APPROACH: Climb to 3000 on the RNAV missed approach route to TRAVA and hold.	
D-ATIS	BUFFALO APP CON	BUFFALO TOWER	GND CON	CLNC DEL	CPDLC
135.35	126.15 263.125	120.5 257.8	133.2 257.8	124.7 257.8	

